


# GUIDE TO APPAREL/TEXTILE CARE SYMBOLS\*

 <p><b>Wash</b></p>	<p><b>Machine Wash Cycles</b></p>  Normal  Permanent Press  Delicate/Gentle  Hand Wash	<p><b>Warning Symbols for Laundering</b></p>  Do Not Wash  Do Not Bleach														
 <p><b>Bleach</b></p>	<p><b>Water Temperatures</b></p> <table border="1"> <tr> <td>(Maximum)</td> <td>(200F)</td> <td>(160F)</td> <td>(140F)</td> <td>(120F)</td> <td>(105F)</td> <td>(65F-85F)</td> </tr> <tr> <td>Symbol(s)</td> <td>95C ●●●●</td> <td>70C ●●●●</td> <td>60C ●●●●</td> <td>50C ●●●●</td> <td>40C ●●</td> <td>30C ●</td> </tr> </table> <p>Any Bleach When Needed</p> <p>Only Non-Chlorine Bleach When Needed</p>	(Maximum)	(200F)	(160F)	(140F)	(120F)	(105F)	(65F-85F)	Symbol(s)	95C ●●●●	70C ●●●●	60C ●●●●	50C ●●●●	40C ●●	30C ●	 Do Not Dry (used with Do Not Wash)  Do Not Iron
(Maximum)	(200F)	(160F)	(140F)	(120F)	(105F)	(65F-85F)										
Symbol(s)	95C ●●●●	70C ●●●●	60C ●●●●	50C ●●●●	40C ●●	30C ●										
 <p><b>Dry</b></p>	<p><b>Tumble Dry Cycles</b></p>  Normal  Permanent Press  Delicate/Gentle  Line Dry / Hang to Dry	<p><b>Additional Instructions (in Symbols or Words)</b></p>  Do Not Wring  Do Not Tumble Dry  Drip Dry  Dry Flat														
 <p><b>Iron</b></p>	<p><b>Iron-Dry or Steam</b></p>  200C (390F) High  150C (300F) Medium  110C (230F) Low	<p><b>In the shade</b> (added to line dry, drip dry, or dry flat)</p>  No Steam (added to iron)														
 <p><b>Dryclean</b></p>	<p><b>Dryclean - Normal Cycle</b></p>  Any Solvent  Any Solvent Except Trichloroethylene  Petroleum Solvent Only  Do Not Dryclean	<p><b>Dryclean - Additional Instructions</b></p>  Short Cycle  Reduced Moisture  Low Heat  No Steam Finishing														

\*This chart illustrates care symbols accepted by the Federal Trade Commission as part of a conditional exemption to the FTC Care Labeling Rule (16 CFR 423). This chart is referenced from ASTM D5489-96c, Fig. 1, Commercial and Home Laundering and Drycleaning Symbols, which illustrates the symbols to use for laundering and drycleaning instructions. As a minimum, laundering instruction shall include, in order, four symbols: washing, bleaching, drying, and ironing; and drycleaning instructions shall include one symbol. Additional words may be used to clarify language-dependent instructions.

We urge you to purchase the latest Annual Book of ASTM Standards that contains the complete symbol set from the American Society for Testing and Materials, 100 Barr Harbor Drive, West Conshohocken, PA 19428-2959.

Distributed by:

**TEXTILE INDUSTRY AFFAIRS**

For free care instruction assistance call:

**850-522-6270** Fax: 212-505-3300

Email: [info@TextileAffairs.org](mailto:info@TextileAffairs.org)

Internet: [www.TextileAffairs.org](http://www.TextileAffairs.org)